

SOA ECM Reprogramming

Logic Change Order	Condition	Vehicle Model/Model Year	Calibration Identification Number (CID)	Appropriate Service Manual
LEGACY				
Logic Change #1	1) Hard Engine Start Cold (Step1) 2) P0464 H-6	01MY Legacy 3.0L	D6JM102B	01MY
Logic Change #2	1) Hard Engine Start Cold (Step2) 2) P0464 H-6	01MY Legacy 3.0L	D6JP000B	01MY
Logic Change #3	P1443 H-6 Includes Logic Change #1~2	01MY Legacy 3.0L	D6HE000B	02MY
Logic Change #4	P030X* H-6 Includes Logic Change #1~3	01~02MY Legacy 3.0L	D6HE100B	02MY
Logic Change #5	1) Hard starting (long crank time) 2) Hesitation Includes Logic Change #1~4	01 MY Legacy 3.0L	D6JR000B	By Year
		02 MY Legacy 3.0L	D6HH000B	
		03 MY Legacy 3.0L	D6QK000B	
		04 MY Legacy 3.0L	D6PC000B	
Logic Change #1	P1507	00~01MY Legacy 2.5L M/T	Not Available	01MY
Logic Change #1	1) P0172	00~01MY Legacy 2.5L	DU2HL0C	01MY
	2) P0065	00~01MY Legacy OBK 2.5L	DU2HK0C	
Logic Change #1	1) P0172	02MY Legacy 2.5L	DU450L05	02MY
	2) P0065	02MY Legacy OBK 2.5L	DU450K05	
Logic Change #1	1) P0172	03MY Legacy 2.5L	D6WQ2GT9	03MY
	2) Hesitation	03MY Legacy OBK 2.5L	D6WQ2OB9	
Logic Change #2	1) P030X* with M/T ONLY	03MY Legacy 2.5L	D6YQ2GTB	03MY
	2) Cold Engine Start/Black Smoke Includes Logic Change #1	03MY Legacy OBK 2.5L	D6YQ2OBB	
Logic Change #3	1) P0172 Includes Logic Change #1~2	03MY Legacy 2.5L	D6YQ2GTC	03MY
		03MY Legacy OBK 2.5L	D6YQ2OBC	
Logic Change #1	1) P0172 (U6) Federal emission specification only	04MY Legacy 2.5L 04MY Legacy OBK & Baja 2.5L	D91P2GT2 D91P2OB2	04MY
Logic Change #2	1) P0464 (U6) Federal emission specification only Includes Logic Change #1	04MY Legacy 2.5L 04MY Legacy OBK & Baja 2.5L	D91P2GT3 D91P2OB3	04MY
Logic Change #1	1) P0464 (U6) Federal emission specification only	05MY Baja 2.5L	DC0N2OB4	05MY
Logic Change #1	1) Surge at 50~80MPH on acceleration 2) P1160 3) Cold Rough Idle in High Altitudes (below 32degF and above 4400 ft)	05MY Baja TURBO	ECM A2WC500K ETC AD3A104D	05MY
WRX				
Logic Change #1	1) P1443 2) P0457 3) P0340	02MY Impreza WRX 2.0L Turbo	A4SGA00C	02MY
Logic Change #2	P0303 Includes Logic Change #1	02MY Impreza WRX 2.0L Turbo	A4SGC00C	02MY
Logic Change #3	Pinging at high rpm (6000) Includes Logic Change #1~2	02MY Impreza WRX 2.0L Turbo	A4SGD10C	02MY
Logic Change #4	Misfire codes during hot restart with engine Temp above 158 deg. F Includes Logic Change #1~3	02MY Impreza WRX 2.0L Turbo M/T	A4SGE00C	02MY
Logic Change #5	Misfire codes during hot restart with engine Temp <u>below</u> 158 deg. F Includes Logic Change #1~4	02MY Impreza WRX 2.0L Turbo M/T	A4SGE01C	02MY
Logic Change #1	Misfire codes during hot restart with engine Temp above 158 deg. F	03MY Impreza WRX 2.0L Turbo M/T	A4TC400L	03MY

SOA ECM Reprogramming

Logic Change #2	Misfire codes during hot restart with engine Temp below 158 deg. F Includes Logic Change #1	03MY Impreza WRX 2.0L Turbo M/T	A4TC401L	03MY
Logic Change #1	Misfire codes during hot restart with engine Temp above 158 deg. F	04MY Impreza WRX 2.0L Turbo M/T	A4TF500F	04MY
Logic Change #2	1) P0139 2) Misfire codes during hot restart with engine Temp below 158 deg. F Includes Logic Change #1	04MY Impreza WRX 2.0L Turbo M/T	A4TF510F	04MY
Logic Change #1	P0139	04MY Impreza WRX 2.0L Turbo Automatic	A4TF510E	04MY
Logic Change #1	1) Pinging during wide open throttle acceleration engine RPM's between 3000-4000	04MY Impreza WRX STi 2.5L Turbo	A2ZJ700J	04MY
Logic Change #2	P0139 Includes Logic Change #1	04MY Impreza WRX STi 2.5L Turbo	A2ZJ710J	04MY
Impreza				
Logic Change #1	P1507	99-01MY Impreza 2.2L M/T	Not Available	01MY
Logic Change #1	1) P0172 2) P0065	00-01MY Impreza 2.5L	DU2HGB3	01MY
Logic Change #1	1) P0172 2) P0065	02MY Impreza 2.5L	DU2HGS3	02MY
Logic Change #1	1) P0172 2) Hesitation	03MY Impreza 2.5L	D6VR2U06	03MY
Logic Change #2	1) P030X* with M/T 2) Cold Engine Start/Black Smoke Includes Logic Change #1	03MY Impreza 2.5L	D6XR2U0B	03MY
Logic Change #3	1) P0172 Includes Logic Change #1-3	03MY Impreza 2.5L	D6XR2U0C	03MY
Logic Change #1	1) Cold Engine Start/Black Smoke	04MY Impreza 2.5L	D86T2U04	04MY
Logic Change #2	1) P0172 Includes Logic Change #1-2	04MY Impreza 2.5L	D86T2U05	04MY
Forester				
Logic Change #1	1) P0172 2) P0065	00-02MY Forester 2.5L M/T 00-02MY Forester 2.5L M/T	DU2HSMD DU2HSAD	02MY
Logic Change #1	1) P0172 2) Hesitation	03MY Forester 2.5L	D6VA2U09	03MY
Logic Change #2	1) P030X* with M/T 2) Cold Engine Start/Black Smoke Includes Logic Change #1	03MY Forester 2.5L	D6XA2U0B	03MY
Logic Change #3	1) P0172 Includes Logic Change #1-3	03MY Forester 2.5L	D6XA2U0C	03MY
Logic Change #1	1) P0172	04MY Forester 2.5L	D86B2U06	04MY

* X=1-4 or 1-6