

[17:20:10.237] EcuFlash Version 1.43.3150
[17:20:10.237] OS Version Windows 7
[17:20:10.237] Qt Version 4.6.2
[17:20:10.237] 62 memory models read.
[17:20:10.237] scanning for metadata models in C:/Program Files (x86)/OpenECU/EcuFlash/rommetadata
[17:20:10.331] 354 ROM metadata models scanned.
[17:20:10.331] checksum module "subarudbw" loaded.
[17:20:10.331] checksum module "mitsucan" loaded.
[17:20:10.331] checksum module "mitsuh8" loaded.
[17:20:10.331] patch module "Subaru CAN Enhanced RAM Parameter Logging" loaded.
[17:20:10.331] patch module "Mitsu CAN RAM Parameter Logging" loaded.
[17:20:10.331] flashing tool "wrx02" loaded.
[17:20:10.331] flashing tool "wrx04" loaded.
[17:20:10.331] flashing tool "sti04" loaded.
[17:20:10.331] flashing tool "sti05" loaded.
[17:20:10.331] flashing tool "mitsukernel" loaded.
[17:20:10.331] flashing tool "mitsukernelocp" loaded.
[17:20:10.331] flashing tool "mitsubootloader" loaded.
[17:20:10.331] flashing tool "shbootmode" loaded.
[17:20:10.331] flashing tool "shaudmode" loaded.
[17:20:10.331] flashing tool "subarucan" loaded.
[17:20:10.331] flashing tool "mitsucan" loaded.
[17:21:07.427] J2534 API Version: 04.04
[17:21:07.427] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:07.427] Device Firmware Version: 1.11.3298
[17:21:07.427] Device Serial Number: TA5KGrZ
[17:21:09.550] kernel get version
[17:21:09.753] interface close
[17:21:09.768] J2534 API Version: 04.04
[17:21:09.768] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:09.768] Device Firmware Version: 1.11.3298
[17:21:09.768] Device Serial Number: TA5KGrZ
[17:21:09.971] interface close
[17:21:09.987] J2534 API Version: 04.04
[17:21:09.987] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:09.987] Device Firmware Version: 1.11.3298
[17:21:09.987] Device Serial Number: TA5KGrZ
[17:21:10.158] SSM2 init
[17:21:10.564] SSM2 init
[17:21:10.673] SSM2 ECU ID is 3D52103005
[17:21:12.701] interface close
[17:21:12.701] interface close
[17:21:21.111] J2534 API Version: 04.04
[17:21:21.111] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:21.111] Device Firmware Version: 1.11.3298
[17:21:21.111] Device Serial Number: TA5KGrZ
[17:21:23.720] kernel get version
[17:21:23.923] interface close
[17:21:23.938] J2534 API Version: 04.04
[17:21:23.938] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:23.938] Device Firmware Version: 1.11.3298
[17:21:23.938] Device Serial Number: TA5KGrZ
[17:21:24.141] interface close
[17:21:24.157] J2534 API Version: 04.04
[17:21:24.157] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:24.157] Device Firmware Version: 1.11.3298
[17:21:24.157] Device Serial Number: TA5KGrZ
[17:21:24.328] SSM2 init
[17:21:24.438] SSM2 ECU ID is 3D52103005
[17:21:26.466] interface close
[17:21:26.481] interface close

[17:21:37.060] J2534 API Version: 04.04
[17:21:37.060] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:37.060] Device Firmware Version: 1.11.3298
[17:21:37.060] Device Serial Number: TA5KrGrZ
[17:21:40.126] kernel get version
[17:21:40.329] interface close
[17:21:40.345] J2534 API Version: 04.04
[17:21:40.345] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:40.345] Device Firmware Version: 1.11.3298
[17:21:40.345] Device Serial Number: TA5KrGrZ
[17:21:40.548] interface close
[17:21:40.579] J2534 API Version: 04.04
[17:21:40.579] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:40.579] Device Firmware Version: 1.11.3298
[17:21:40.579] Device Serial Number: TA5KrGrZ
[17:21:40.766] SSM2 init
[17:21:40.875] SSM2 ECU ID is 3D52103005
[17:21:42.903] interface close
[17:21:42.919] interface close
[17:21:55.395] J2534 API Version: 04.04
[17:21:55.395] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:21:55.395] Device Firmware Version: 1.11.3298
[17:21:55.395] Device Serial Number: TA5KrGrZ
[17:21:58.259] denso02_bootloader_cmd_start
[17:21:59.491] denso02_bootloader_cmd_start
[17:22:00.724] denso02_bootloader_cmd_start
[17:22:01.956] denso02_bootloader_cmd_start
[17:22:03.188] denso02_bootloader_cmd_start
[17:22:03.610] kernel get version
[17:22:03.922] interface close
[17:22:03.922] interface close
[17:23:27.488] J2534 API Version: 04.04
[17:23:27.488] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:27.488] Device Firmware Version: 1.11.3298
[17:23:27.488] Device Serial Number: TA5KrGrZ
[17:23:34.309] kernel get version
[17:23:34.511] interface close
[17:23:34.543] J2534 API Version: 04.04
[17:23:34.543] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:34.543] Device Firmware Version: 1.11.3298
[17:23:34.543] Device Serial Number: TA5KrGrZ
[17:23:34.730] interface close
[17:23:34.761] J2534 API Version: 04.04
[17:23:34.761] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:34.761] Device Firmware Version: 1.11.3298
[17:23:34.761] Device Serial Number: TA5KrGrZ
[17:23:34.948] SSM2 init
[17:23:35.057] SSM2 ECU ID is 3D52103005
[17:23:37.085] interface close
[17:23:37.085] interface close
[17:23:43.144] J2534 API Version: 04.04
[17:23:43.144] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:43.144] Device Firmware Version: 1.11.3298
[17:23:43.144] Device Serial Number: TA5KrGrZ
[17:23:45.696] kernel get version
[17:23:45.899] interface close
[17:23:45.915] J2534 API Version: 04.04
[17:23:45.915] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:45.915] Device Firmware Version: 1.11.3298
[17:23:45.915] Device Serial Number: TA5KrGrZ

[17:23:46.117] interface close
[17:23:46.133] J2534 API Version: 04.04
[17:23:46.133] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:46.133] Device Firmware Version: 1.11.3298
[17:23:46.133] Device Serial Number: TA5KrGrZ
[17:23:46.305] SSM2 init
[17:23:46.414] SSM2 ECU ID is 3D52103005
[17:23:48.442] interface close
[17:23:48.457] interface close
[17:23:54.044] J2534 API Version: 04.04
[17:23:54.044] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:54.044] Device Firmware Version: 1.11.3298
[17:23:54.044] Device Serial Number: TA5KrGrZ
[17:23:55.722] kernel get version
[17:23:55.925] interface close
[17:23:55.941] J2534 API Version: 04.04
[17:23:55.941] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:55.941] Device Firmware Version: 1.11.3298
[17:23:55.941] Device Serial Number: TA5KrGrZ
[17:23:56.143] interface close
[17:23:56.159] J2534 API Version: 04.04
[17:23:56.159] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:23:56.159] Device Firmware Version: 1.11.3298
[17:23:56.159] Device Serial Number: TA5KrGrZ
[17:23:56.331] SSM2 init
[17:23:56.736] SSM2 init
[17:23:56.845] SSM2 ECU ID is 3D52103005
[17:23:58.873] interface close
[17:23:58.873] interface close
[17:24:14.896] J2534 API Version: 04.04
[17:24:14.896] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:24:14.896] Device Firmware Version: 1.11.3298
[17:24:14.896] Device Serial Number: TA5KrGrZ
[17:24:16.731] kernel get version
[17:24:16.933] interface close
[17:24:16.965] J2534 API Version: 04.04
[17:24:16.965] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:24:16.965] Device Firmware Version: 1.11.3298
[17:24:16.965] Device Serial Number: TA5KrGrZ
[17:24:17.152] interface close
[17:24:17.183] J2534 API Version: 04.04
[17:24:17.183] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:24:17.183] Device Firmware Version: 1.11.3298
[17:24:17.183] Device Serial Number: TA5KrGrZ
[17:24:17.370] SSM2 init
[17:24:17.479] SSM2 ECU ID is 3D52103005
[17:24:19.507] interface close
[17:24:19.523] interface close
[17:24:27.190] J2534 API Version: 04.04
[17:24:27.190] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:24:27.190] Device Firmware Version: 1.11.3298
[17:24:27.190] Device Serial Number: TA5KrGrZ
[17:24:29.986] denso02_bootloader_cmd_start
[17:24:31.218] denso02_bootloader_cmd_start
[17:24:32.451] denso02_bootloader_cmd_start
[17:24:33.683] denso02_bootloader_cmd_start
[17:24:34.915] denso02_bootloader_cmd_start
[17:24:35.337] kernel get version
[17:24:35.649] interface close
[17:24:35.664] interface close
[17:24:46.695] J2534 API Version: 04.04

[17:24:46.695] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:24:46.695] Device Firmware Version: 1.11.3298
[17:24:46.695] Device Serial Number: TA5KrGrZ
[17:24:48.803] denso02_bootloader_cmd_start
[17:24:50.036] denso02_bootloader_cmd_start
[17:24:51.268] denso02_bootloader_cmd_start
[17:24:52.482] denso02_bootloader_cmd_start
[17:24:53.716] denso02_bootloader_cmd_start
[17:24:54.137] kernel get version
[17:24:54.449] interface close
[17:24:54.449] interface close
[17:25:01.461] J2534 API Version: 04.04
[17:25:01.461] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:25:01.461] Device Firmware Version: 1.11.3298
[17:25:01.461] Device Serial Number: TA5KrGrZ
[17:25:04.397] denso02_bootloader_cmd_start
[17:25:05.630] denso02_bootloader_cmd_start
[17:25:06.862] denso02_bootloader_cmd_start
[17:25:08.095] denso02_bootloader_cmd_start
[17:25:09.327] denso02_bootloader_cmd_start
[17:25:09.748] kernel get version
[17:25:10.060] interface close
[17:25:10.060] interface close
[17:25:18.345] J2534 API Version: 04.04
[17:25:18.345] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:25:18.345] Device Firmware Version: 1.11.3298
[17:25:18.345] Device Serial Number: TA5KrGrZ
[17:25:21.163] kernel get version
[17:25:21.365] interface close
[17:25:21.397] J2534 API Version: 04.04
[17:25:21.397] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:25:21.397] Device Firmware Version: 1.11.3298
[17:25:21.397] Device Serial Number: TA5KrGrZ
[17:25:21.584] interface close
[17:25:21.599] J2534 API Version: 04.04
[17:25:21.599] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:25:21.599] Device Firmware Version: 1.11.3298
[17:25:21.599] Device Serial Number: TA5KrGrZ
[17:25:21.771] SSM2 init
[17:25:21.880] SSM2 ECU ID is 3D52103005
[17:25:23.908] interface close
[17:25:23.908] interface close
[17:26:23.564] J2534 API Version: 04.04
[17:26:23.564] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:23.564] Device Firmware Version: 1.11.3298
[17:26:23.564] Device Serial Number: TA5KrGrZ
[17:26:25.695] kernel get version
[17:26:25.898] readback fail
[17:26:25.898] interface close
[17:26:25.913] J2534 API Version: 04.04
[17:26:25.913] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:25.913] Device Firmware Version: 1.11.3298
[17:26:25.913] Device Serial Number: TA5KrGrZ
[17:26:25.991] interface close
[17:26:26.007] J2534 API Version: 04.04
[17:26:26.007] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:26.007] Device Firmware Version: 1.11.3298
[17:26:26.007] Device Serial Number: TA5KrGrZ
[17:26:26.179] SSM2 init
[17:26:26.584] readback fail

[17:26:26.584] SSM2 init
[17:26:26.990] readback fail
[17:26:26.990] SSM2 init
[17:26:27.395] readback fail
[17:26:27.395] SSM2 init
[17:26:27.801] readback fail
[17:26:27.801] SSM2 init
[17:26:28.207] readback fail
[17:26:28.207] SSM2 init
[17:26:28.612] readback fail
[17:26:28.612] SSM2 init
[17:26:29.018] readback fail
[17:26:29.018] SSM2 init
[17:26:29.423] readback fail
[17:26:29.423] SSM2 init
[17:26:29.829] readback fail
[17:26:29.829] SSM2 init
[17:26:30.235] readback fail
[17:26:30.344] interface close
[17:26:30.344] interface close
[17:26:38.374] J2534 API Version: 04.04
[17:26:38.374] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:38.374] Device Firmware Version: 1.11.3298
[17:26:38.374] Device Serial Number: TA5KrGrZ
[17:26:40.218] kernel get version
[17:26:40.421] readback fail
[17:26:40.421] interface close
[17:26:40.437] J2534 API Version: 04.04
[17:26:40.437] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:40.437] Device Firmware Version: 1.11.3298
[17:26:40.437] Device Serial Number: TA5KrGrZ
[17:26:40.515] interface close
[17:26:40.530] J2534 API Version: 04.04
[17:26:40.530] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:40.530] Device Firmware Version: 1.11.3298
[17:26:40.530] Device Serial Number: TA5KrGrZ
[17:26:40.702] SSM2 init
[17:26:41.108] readback fail
[17:26:41.108] SSM2 init
[17:26:41.513] readback fail
[17:26:41.513] SSM2 init
[17:26:41.919] readback fail
[17:26:41.919] SSM2 init
[17:26:42.324] readback fail
[17:26:42.324] SSM2 init
[17:26:42.730] readback fail
[17:26:42.730] SSM2 init
[17:26:43.136] readback fail
[17:26:43.136] SSM2 init
[17:26:43.541] readback fail
[17:26:43.541] SSM2 init
[17:26:43.947] readback fail
[17:26:43.947] SSM2 init
[17:26:44.352] readback fail
[17:26:44.352] SSM2 init
[17:26:44.758] readback fail
[17:26:44.867] interface close
[17:26:44.867] interface close
[17:26:58.964] J2534 API Version: 04.04
[17:26:58.964] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:26:58.964] Device Firmware Version: 1.11.3298

[17:26:58.964] Device Serial Number: TA5KrGrZ
[17:27:01.438] kernel get version
[17:27:01.641] interface close
[17:27:01.672] J2534 API Version: 04.04
[17:27:01.672] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:01.672] Device Firmware Version: 1.11.3298
[17:27:01.672] Device Serial Number: TA5KrGrZ
[17:27:01.860] interface close
[17:27:01.875] J2534 API Version: 04.04
[17:27:01.875] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:01.875] Device Firmware Version: 1.11.3298
[17:27:01.875] Device Serial Number: TA5KrGrZ
[17:27:02.047] SSM2 init
[17:27:02.156] SSM2 ECU ID is 3D52103005
[17:27:04.184] interface close
[17:27:04.184] interface close
[17:27:11.798] J2534 API Version: 04.04
[17:27:11.798] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:11.798] Device Firmware Version: 1.11.3298
[17:27:11.798] Device Serial Number: TA5KrGrZ
[17:27:13.461] kernel get version
[17:27:13.664] interface close
[17:27:13.680] J2534 API Version: 04.04
[17:27:13.680] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:13.680] Device Firmware Version: 1.11.3298
[17:27:13.680] Device Serial Number: TA5KrGrZ
[17:27:13.882] interface close
[17:27:13.914] J2534 API Version: 04.04
[17:27:13.914] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:13.914] Device Firmware Version: 1.11.3298
[17:27:13.914] Device Serial Number: TA5KrGrZ
[17:27:14.085] SSM2 init
[17:27:14.194] SSM2 ECU ID is 3D52103005
[17:27:16.222] interface close
[17:27:16.222] interface close
[17:27:27.503] J2534 API Version: 04.04
[17:27:27.503] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:27.503] Device Firmware Version: 1.11.3298
[17:27:27.503] Device Serial Number: TA5KrGrZ
[17:27:29.322] kernel get version
[17:27:29.524] interface close
[17:27:29.540] J2534 API Version: 04.04
[17:27:29.540] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:29.540] Device Firmware Version: 1.11.3298
[17:27:29.540] Device Serial Number: TA5KrGrZ
[17:27:29.743] interface close
[17:27:29.758] J2534 API Version: 04.04
[17:27:29.758] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:29.758] Device Firmware Version: 1.11.3298
[17:27:29.758] Device Serial Number: TA5KrGrZ
[17:27:29.930] SSM2 init
[17:27:30.039] SSM2 ECU ID is 3D52103005
[17:27:32.067] interface close
[17:27:32.067] interface close
[17:27:37.539] J2534 API Version: 04.04
[17:27:37.539] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:37.539] Device Firmware Version: 1.11.3298
[17:27:37.539] Device Serial Number: TA5KrGrZ
[17:27:39.022] kernel get version
[17:27:39.225] interface close

[17:27:39.241] J2534 API Version: 04.04
[17:27:39.241] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:39.241] Device Firmware Version: 1.11.3298
[17:27:39.241] Device Serial Number: TA5KrGrZ
[17:27:39.444] interface close
[17:27:39.459] J2534 API Version: 04.04
[17:27:39.459] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:39.459] Device Firmware Version: 1.11.3298
[17:27:39.459] Device Serial Number: TA5KrGrZ
[17:27:39.631] SSM2 init
[17:27:39.740] SSM2 ECU ID is 3D52103005
[17:27:41.768] interface close
[17:27:41.768] interface close
[17:27:47.776] J2534 API Version: 04.04
[17:27:47.776] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:27:47.776] Device Firmware Version: 1.11.3298
[17:27:47.776] Device Serial Number: TA5KrGrZ
[17:27:50.172] denso02_bootloader_cmd_start
[17:27:51.404] denso02_bootloader_cmd_start
[17:27:52.636] denso02_bootloader_cmd_start
[17:27:53.869] denso02_bootloader_cmd_start
[17:27:55.101] denso02_bootloader_cmd_start
[17:27:55.522] kernel get version
[17:27:55.834] interface close
[17:27:55.834] interface close
[17:28:16.756] J2534 API Version: 04.04
[17:28:16.756] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:28:16.756] Device Firmware Version: 1.11.3298
[17:28:16.756] Device Serial Number: TA5KrGrZ
[17:28:18.262] kernel get version
[17:28:18.465] interface close
[17:28:18.496] J2534 API Version: 04.04
[17:28:18.496] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:28:18.496] Device Firmware Version: 1.11.3298
[17:28:18.496] Device Serial Number: TA5KrGrZ
[17:28:18.684] interface close
[17:28:18.699] J2534 API Version: 04.04
[17:28:18.699] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:28:18.699] Device Firmware Version: 1.11.3298
[17:28:18.699] Device Serial Number: TA5KrGrZ
[17:28:18.871] SSM2 init
[17:28:18.980] SSM2 ECU ID is 3D52103005
[17:28:21.008] interface close
[17:28:21.024] interface close
[17:31:41.556] J2534 API Version: 04.04
[17:31:41.556] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:31:41.556] Device Firmware Version: 1.11.3298
[17:31:41.556] Device Serial Number: TA5KrGrZ
[17:31:43.702] kernel get version
[17:31:43.905] interface close
[17:31:43.921] J2534 API Version: 04.04
[17:31:43.921] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:31:43.921] Device Firmware Version: 1.11.3298
[17:31:43.921] Device Serial Number: TA5KrGrZ
[17:31:44.124] interface close
[17:31:44.139] J2534 API Version: 04.04
[17:31:44.139] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:31:44.139] Device Firmware Version: 1.11.3298
[17:31:44.139] Device Serial Number: TA5KrGrZ
[17:31:44.311] SSM2 init
[17:31:44.420] SSM2 ECU ID is 3D52103005

[17:31:46.448] interface close
[17:31:46.464] interface close
[17:31:54.213] J2534 API Version: 04.04
[17:31:54.213] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:31:54.213] Device Firmware Version: 1.11.3298
[17:31:54.213] Device Serial Number: TA5KrGrZ
[17:31:55.969] kernel get version
[17:31:56.172] interface close
[17:31:56.188] J2534 API Version: 04.04
[17:31:56.188] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:31:56.188] Device Firmware Version: 1.11.3298
[17:31:56.188] Device Serial Number: TA5KrGrZ
[17:31:56.390] interface close
[17:31:56.406] J2534 API Version: 04.04
[17:31:56.406] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:31:56.406] Device Firmware Version: 1.11.3298
[17:31:56.406] Device Serial Number: TA5KrGrZ
[17:31:56.578] SSM2 init
[17:31:56.687] SSM2 ECU ID is 3D52103005
[17:31:58.715] interface close
[17:31:58.715] interface close
[17:32:03.069] J2534 API Version: 04.04
[17:32:03.069] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:32:03.069] Device Firmware Version: 1.11.3298
[17:32:03.069] Device Serial Number: TA5KrGrZ
[17:32:05.553] denso02_bootloader_cmd_start
[17:32:06.785] denso02_bootloader_cmd_start
[17:32:08.018] denso02_bootloader_cmd_start
[17:32:09.250] denso02_bootloader_cmd_start
[17:32:10.482] denso02_bootloader_cmd_start
[17:32:10.904] kernel get version
[17:32:11.216] interface close
[17:32:11.216] interface close
[17:32:18.336] J2534 API Version: 04.04
[17:32:18.336] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:32:18.336] Device Firmware Version: 1.11.3298
[17:32:18.336] Device Serial Number: TA5KrGrZ
[17:32:20.332] kernel get version
[17:32:20.535] interface close
[17:32:20.566] J2534 API Version: 04.04
[17:32:20.566] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:32:20.566] Device Firmware Version: 1.11.3298
[17:32:20.566] Device Serial Number: TA5KrGrZ
[17:32:20.754] interface close
[17:32:20.785] J2534 API Version: 04.04
[17:32:20.785] J2534 DLL Version: 1.00.3147 Sep 3 2010 00:11:07
[17:32:20.785] Device Firmware Version: 1.11.3298
[17:32:20.785] Device Serial Number: TA5KrGrZ
[17:32:20.972] SSM2 init
[17:32:21.081] SSM2 ECU ID is 3D52103005
[17:32:23.109] interface close
[17:32:23.109] interface close